

Generating a Pad




This task shows you how to create a pad from the profile previously created. For this, you will leave the Sketcher workbench and automatically enter Part Design workbench.



1. Click the Exit icon .

You are now in Part Design workbench. If this is not the case, select `Start -> Mechanical Design -> Part Design` from the menu bar.

The sketched profile appears as follows:




2. Click the Pad icon .

The Pad Definition dialog box appears.

3. Enter `5mm` as the pad Length.

4. Click `OK`.



The pad appears as shown here:

